TPO \$62,022159.

PATENT

NOV 1 6 2007

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

)

Examiner: R. Patel

November 15, 2007

Group Art Unit: 2838

	•
SEIJI KUROKAMI, et al.)

Appl. No.: 09/818,604

Filed: March 28, 2001

For: POWER CONVERTING
APPARATUS, CONTROL
METHOD THEREFOR, AND
SOLAR POWER GENERATION
APPARATUS

U.S. Patent No.: 7,079,406 B2

Issued: July 18, 2006

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450 OF COFFECTION

REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

11/19/2007 JADDO1

00000065 7079406

01 FC:1811

100.00 OP

Patentees' undersigned attorney may be reached in our Costa Mesa, California office by telephone at (714) 540-8700. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Frank L. Cire

Attorney for Patentees Registration No.: 42,419

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 Facsimile: (212) 218-2200

FCHS_WS 852199v1

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

7,079,406 B2

DATED

July 18, 2006

INVENTOR(S) :

Seiji Kurokami, et al.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COVER PAGE:

(56) References Cited, FOREIGN PATENT DOCUMENTS

"09 084254" should read -- 09-084254 --;

"09 285015" should read -- 09-285015 --; and

"2000 023371" should read -- 2000-023371 --.

COLUMN 2:

Line 29, "a, DC" should read -- a DC --.

COLUMN 3:

Lines 17 and 47, "(an" should read -- (a --.

COLUMN 5:

Line 57, "(an" should read -- (a --.

COLUMN 9:

Line 32, "to-the" should read -- to the --.

COLUMN 10:

Line 13, "(an" should read -- (a --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. <u>7,079,406 B2</u>

No. of add'l. copies

No. of add'l. copies @ 30¢ per page

pin 1 2 7 7007

 \Rightarrow

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

7,079,406 B2

DATED

July 18, 2006

INVENTOR(S) :

Seiji Kurokami, et al.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 11:

Line 57, "lager" should read -- larger --.

COLUMN 12:

Line 27, "(an" should read -- (a --.

COLUMN 18:

Line 20, "Ti" should read -- T1 --; and

Line 37, insert a paragraph break before "con-".

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

161 27 2007

Form PTO 1050 (Rev. 3-82) 124821 (Form#30)

@ 30¢ per page

PATENT NO. 7,079,406 B2

No. of add'l. copies

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

7,079,406 B2

DATED

July 18, 2006

INVENTOR(S) :

Seiji Kurokami, et al.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COVER PAGE:

(56) References Cited, FOREIGN PATENT DOCUMENTS

"09 084254" should read -- 09-084254 --;

"09 285015" should read -- 09-285015 --; and

"2000 023371" should read -- 2000-023371 --.

COLUMN 2:

Line 29, "a, DC" should read -- a DC --.

COLUMN 3:

Lines 17 and 47, "(an" should read -- (a --.

COLUMN 5:

Line 57, "(an" should read -- (a --.

COLUMN 9:

Line 32, "to-the" should read -- to the --.

COLUMN 10:

Line 13, "(an" should read -- (a --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

PATENT NO. 7,079,406 B2

NOV 27 2007

No. of add'l. copies

@ 30¢ per page

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

7,079,406 B2

DATED

July 18, 2006

INVENTOR(S) :

Seiji Kurokami, et al.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 11:

Line 57, "lager" should read -- larger --.

COLUMN 12:

Line 27, "(an" should read -- (a --.

COLUMN 18:

Line 20, "Ti" should read -- T1 --; and Line 37, insert a paragraph break before "con-".

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

NOV 27 2007 ⇒ .

PATENT NO. 7,079,406 B2

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82) 124821 (Form#30)